

Aiken Technical College
Radiation Protection Technology Program
Radiation Work Permit
 (For Training Purposes Only—No Actual Hazards Exist)



Purpose: RP Personnel only—Enter Airborne Radioactivity Areas	RWP# : 201X-243 Rev: 0
Task # 6 Enter Airborne Radioactivity Areas	

Protective Clothing Requirements

<input checked="" type="checkbox"/> None Required			
<input checked="" type="checkbox"/> Partials consisting of: shoe covers and 2 pair of vinyl gloves			
<input checked="" type="checkbox"/> Full Set	<input checked="" type="checkbox"/> Cloth:	<input type="checkbox"/> Plastic:	<input type="checkbox"/> Paper:
			<input checked="" type="checkbox"/> with extra: gloves
<input type="checkbox"/> Double Set	<input type="checkbox"/> Cloth:	<input type="checkbox"/> Plastic:	<input type="checkbox"/> Paper:
			<input type="checkbox"/> with extra:
<input checked="" type="checkbox"/> Other: PCs based on posted or anticipated conditions			

Respiratory Protection Requirements

<input type="checkbox"/> None Required
<input checked="" type="checkbox"/> Full Face Negative Pressure Respirator with: <input type="checkbox"/> Particulate <input type="checkbox"/> Iodine <input type="checkbox"/> Other:
<input checked="" type="checkbox"/> Other: Full face negative pressure is minimum required. Supervisor may provide additional requirements

Contamination Control Requirements

Remove all PC prior to exiting across a step-off pad
Bag respirator face-piece upon removal—label with name of user
Perform a hand and foot frisk upon leaving the posted RCA
Frisk all material which has been in a CA prior to removal from the posted RCA

Aiken Technical College
Radiation Protection Technology Program
Radiation Work Permit
 (For Training Purposes Only—No Actual Hazards Exist)



Purpose: RP Personnel only—Enter Airborne Radioactivity Areas	RWP# : 201X-243 Rev: 0
Task # 6 Enter Airborne Radioactivity Areas	

RP Hold Points

<p>Evidence of elevated dose rates above the posting for the area</p> <p>Opening any contaminated system is not permitted</p>

Stop Work Criteria

<p>Dose rates exceed posting for the area</p> <p>Leak of radioactive fluids into uncontrolled areas</p>

Additional Requirements

<p>Minimum 10 minute grab air sample required for each entry into a posted Airborne Radioactivity Area unless exempted by the supervisor.</p> <p>Entry into posted LHRA s not permitted on this RWP.</p>
--